



ERA Software to Hardware Mapping

Current for V5.80.0

Headend

ERA Software to Hardware Mapping

Classification	Region	ID	Description	Minimum SW Requirements	Latest Supported Version	Replacement
Master Unit	All	7635443-00	WCS-2 Subrack	1.8.0	5.80 Drop 6	7635443-03
Master Unit	All	7635443-01	WCS-2 Subrack	2.6.0	5.80 Drop 6	
Master Unit	All	7635443-03	WCS-2 Subrack	5.50 Drop 6	5.80 Drop 6	
Master Unit	All	7844067-00	WCS-2 Subrack, -48Vdc	2.8.3	5.80 Drop 6	
Master Unit	All	7844067-02	WCS-2 Subrack, -48Vdc	5.50 Drop 6	5.80 Drop 6	
Master Unit	All	7635442-00	WCS-4 Subrack	1.6.0	5.80 Drop 6	7635442-03
Master Unit	All	7635442-01	WCS-4 Subrack	2.6.0	5.80 Drop 6	
Master Unit	All	7635442-03	WCS-4 Subrack	5.50 Drop 6	5.80 Drop 6	
Master Unit	All	7844068-00	WCS-4 Subrack, -48Vdc	2.8.3	5.80 Drop 6	7844068-02
Master Unit	All	7844068-02	WCS-4 Subrack, -48Vdc	5.50 Drop 6	5.80 Drop 6	
Master Unit	All	7633229-00	RFD, RF Donor	1.6.0	5.80 Drop 6	7633229-05
Master Unit	All	7633229-01	RFD, RF Donor	1.6.0	5.80 Drop 6	7633229-05
Master Unit	All	7633229-02	RFD, RF Donor	1.6.0	5.80 Drop 6	7633229-05
Master Unit	All	7633229-03	RFD, RF Donor	2.8.0.400	5.80 Drop 6	
Master Unit	All	7633229-05	RFD, RF Donor	2.8.0.400	5.80 Drop 6	
Master Unit	All	7841277-00	RFD HB, RF Donor	3.0.0	5.80 Drop 6	
Master Unit	All	7633228-00	CAT, Copper Transport	1.6.0	5.80 Drop 6	7633228-03
Master Unit	All	7633228-01	CAT, Copper Transport	1.6.0	5.80 Drop 6	7633228-03
Master Unit	All	7633228-02	CAT, Copper Transport	2.6.0	5.80 Drop 6	
Master Unit	All	7633228-03	CAT, Copper Transport	5.50 Drop 6	5.80 Drop 6	
Master Unit	All	7847569-00	CAT2, Copper Transport for 2nd Gen AP	4.15.10	5.80 Drop 6	
Master Unit	All	7847569-01	CAT2, Copper Transport for 2nd Gen AP	5.50 Drop 6	5.80 Drop 6	
Master Unit	All	7642123-00	OPT, Optical Transport	1.6.0	5.80 Drop 6	7642123-01
Master Unit	All	7642123-01	OPT, Optical Transport	2.8.0	5.80 Drop 6	
Master Unit	All	7642125-00	SUI, System Interface	1.6.0	5.80 Drop 6	
Master Unit	All	7642132-00	AUT, Auxiliary Transport	1.8.1	5.80 Drop 6	None
Master Unit	All	7721916-00	CDD, CPRI Digital Donor	2.0.0	5.80 Drop 6	7721916-02
Master Unit	All	7721916-01	CDD, CPRI Digital Donor	2.0.0	5.80 Drop 6	7721916-02
Master Unit	All	7721916-02	CDD, CPRI Digital Donor	2.0.0	5.80 Drop 6	
Master Unit	All	7721916-03	CDD2, CPRI Digital Donor	5.50 Drop 6	5.80 Drop 6	
Master Unit	All	7693531-00	PSU Shelf, AC	1.6.0	5.80 Drop 6	
Master Unit	All	7676311-00	e-POI Subrack + IFC	1.6.0	5.80 Drop 6	7676311-01
Master Unit	All	7676311-01	e-POI Subrack + IFC	1.6.0	5.80 Drop 6	
Master Unit	All	7851464-00	ORD, ERA O-RAN DONOR	5.80 Drop 6	5.80 Drop 6	

Access Points ERA Software to Hardware Mapping

Classification	Region	ID	Description	Minimum SW Requirements	Latest Supported Version	Replacement
UAP						
Access Point	All	7642133-01 (Rev < 8)	UAP	1.8.1	5.80 Drop 6	7642133-01 (Rev 8)
Access Point	All	7642133-01 (Rev 8)	UAP (EOL replacement)*	4.15.10	5.80 Drop 6	None
Access Point	All	7724746-00	UAP-X	2.0.0	5.80 Drop 6	None
Access Point	All	7768763-00	UAP-N25	2.4.0	5.80 Drop 6	None
Access Point	All	7777908-00	UAP-XN25	2.4.0	5.80 Drop 6	None

*UAP EOL replacement can be identified by the serial number on the back of the unit. The 11th Digit shows an A for the original UAP unit, and a B or C for the UAP EOL variant.

CAP L						
Access Point	EMEA	7834677-0005	CAP L 4A/18/21/26 C-DC	2.7.0	5.80 Drop 6	None
Access Point	EMEA	7834677-0002	CAP L 4A/18/21/26 C-DC-F1	2.7.0	5.80 Drop 6	None
Access Point	EMEA	7834677-0004	CAP L 4A/18/21/26 C-PE	2.7.0	5.80 Drop 6	
Access Point	EMEA	7834677-0001	CAP L 4A/18/21/26 C-PE-F1	2.7.0	5.80 Drop 6	7834677-0004
Access Point	EMEA	7834677-0006	CAP L 4A/18/21/26 F-DC	2.7.0	5.80 Drop 6	
Access Point	EMEA	7834677-0003	CAP L 4A/18/21/26 F-DC-F1	2.7.0	5.80 Drop 6	7834677-0006
Access Point	EMEA	7776643-0005	CAP L 8/18/21/26 C-DC	2.3.0	5.80 Drop 6	None
Access Point	EMEA	7776643-0002	CAP L 8/18/21/26 C-DC-F1	2.3.0	5.80 Drop 6	None
Access Point	EMEA	7776643-0004	CAP L 8/18/21/26 C-PE	2.3.0	5.80 Drop 6	
Access Point	EMEA	7776643-0001	CAP L 8/18/21/26 C-PE-F1	2.3.0	5.80 Drop 6	7776643-0004
Access Point	EMEA	7776643-0006	CAP L 8/18/21/26 F-DC	2.3.0	5.80 Drop 6	
Access Point	EMEA	7776643-0003	CAP L 8/18/21/26 F-DC-F1	2.3.0	5.80 Drop 6	7776643-0006
Access Point	EMEA	7776641-0005	CAP L 8/9/18/21 C-DC	2.3.0	5.80 Drop 6	None
Access Point	EMEA	7776641-0002	CAP L 8/9/18/21 C-DC-F1	2.3.0	5.80 Drop 6	None
Access Point	EMEA	7776641-0004	CAP L 8/9/18/21 C-PE	2.3.0	5.80 Drop 6	
Access Point	EMEA	7776641-0001	CAP L 8/9/18/21 C-PE-F1	2.3.0	5.80 Drop 6	7776641-0004
Access Point	EMEA	7776641-0006	CAP L 8/9/18/21 F-DC	2.3.0	5.80 Drop 6	
Access Point	EMEA	7776641-0003	CAP L 8/9/18/21 F-DC-F1	2.3.0	5.80 Drop 6	7776641-0006
Access Point	EMEA	7776595-0005	CAP L 9/18/18/21 C-DC	2.3.0	5.80 Drop 6	None
Access Point	EMEA	7776595-0002	CAP L 9/18/18/21 C-DC-F1	2.3.0	5.80 Drop 6	None
Access Point	EMEA	7776595-0004	CAP L 9/18/18/21 C-PE	2.3.0	5.80 Drop 6	
Access Point	EMEA	7776595-0001	CAP L 9/18/18/21 C-PE-F1	2.3.0	5.80 Drop 6	7776595-0004
Access Point	EMEA	7776595-0006	CAP L 9/18/18/21 F-DC	2.3.0	5.80 Drop 6	
Access Point	EMEA	7776595-0003	CAP L 9/18/18/21 F-DC-F1	2.3.0	5.80 Drop 6	7776595-0006
Access Point	EMEA	7776598-0005	CAP L 9/18/21/26 C-DC	2.3.0	5.80 Drop 6	None
Access Point	EMEA	7776598-0002	CAP L 9/18/21/26 C-DC-F1	2.3.0	5.80 Drop 6	None
Access Point	EMEA	7776598-0004	CAP L 9/18/21/26 C-PE	2.3.0	5.80 Drop 6	
Access Point	EMEA	7776598-0001	CAP L 9/18/21/26 C-PE-F1	2.3.0	5.80 Drop 6	7776598-0004
Access Point	EMEA	7776598-0006	CAP L 9/18/21/26 F-DC	2.3.0	5.80 Drop 6	
Access Point	EMEA	7776598-0003	CAP L 9/18/21/26 F-DC-F1	2.3.0	5.80 Drop 6	7776598-0006
Access Point	EMEA	7770209-0005	CAP L 18/21/26/26 C-DC	2.3.0	5.80 Drop 6	None
Access Point	EMEA	7770209-0002	CAP L 18/21/26/26 C-DC-F1	2.3.0	5.80 Drop 6	None

Access Points ERA Software to Hardware Mapping

Classification	Region	ID	Description	Minimum SW Requirements	Latest Supported Version	Replacement
Access Point	EMEA	7770209-0004	CAP L 18/21/26/26 C-PE	2.3.0	5.80 Drop 6	
Access Point	EMEA	7770209-0001	CAP L 18/21/26/26 C-PE-F1	2.3.0	5.80 Drop 6	7770209-0004
Access Point	EMEA	7770209-0006	CAP L 18/21/26/26 F-DC	2.3.0	5.80 Drop 6	
Access Point	EMEA	7770209-0003	CAP L 18/21/26/26 F-DC-F1	2.3.0	5.80 Drop 6	7770209-0006
Access Point	NAR	7776596-0005	CAP L 7/80-85/17E/19 C-DC	2.3.0	5.80 Drop 6	None
Access Point	NAR	7776596-0002	CAP L 7/80-85/17E/19 C-DC-F1	2.3.0	5.80 Drop 6	None
Access Point	NAR	7776596-0004	CAP L 7/80-85/17E/19 C-PE	2.3.0	5.80 Drop 6	
Access Point	NAR	7776596-0001	CAP L 7/80-85/17E/19 C-PE-F1	2.3.0	5.80 Drop 6	7776596-0004
Access Point	NAR	7776596-0006	CAP L 7/80-85/17E/19 F-DC	2.3.0	5.80 Drop 6	
Access Point	NAR	7776596-0003	CAP L 7/80-85/17E/19 F-DC-F1	2.3.0	5.80 Drop 6	7776596-0006
Access Point	NAR	7770356-0005	CAP L 17E/17E/19/19 C-DC	2.3.0	5.80 Drop 6	None
Access Point	NAR	7770356-0002	CAP L 17E/17E/19/19 C-DC-F1	2.3.0	5.80 Drop 6	None
Access Point	NAR	7770356-0004	CAP L 17E/17E/19/19 C-PE	2.3.0	5.80 Drop 6	
Access Point	NAR	7770356-0001	CAP L 17E/17E/19/19 C-PE-F1	2.3.0	5.80 Drop 6	7770356-0004
Access Point	NAR	7770356-0006	CAP L 17E/17E/19/19 F-DC	2.3.0	5.80 Drop 6	
Access Point	NAR	7770356-0003	CAP L 17E/17E/19/19 F-DC-F1	2.3.0	5.80 Drop 6	7770356-0006
Access Point	NAR	7770203-0005	CAP L 17E/17E/23/23 C-DC	2.3.0	5.80 Drop 6	None
Access Point	NAR	7770203-0002	CAP L 17E/17E/23/23 C-DC-F1	2.3.0	5.80 Drop 6	None
Access Point	NAR	7770203-0004	CAP L 17E/17E/23/23 C-PE	2.3.0	5.80 Drop 6	
Access Point	NAR	7770203-0001	CAP L 17E/17E/23/23 C-PE-F1	2.3.0	5.80 Drop 6	7770203-0004
Access Point	NAR	7770203-0006	CAP L 17E/17E/23/23 F-DC	2.3.0	5.80 Drop 6	
Access Point	NAR	7770203-0003	CAP L 17E/17E/23/23 F-DC-F1	2.3.0	5.80 Drop 6	7770203-0006
Access Point	NAR	7776597-0005	CAP L 17E/19/23/25T C-DC	2.3.1	5.80 Drop 6	None
Access Point	NAR	7776597-0002	CAP L 17E/19/23/25T C-DC-F1	2.3.1	5.80 Drop 6	None
Access Point	NAR	7776597-0004	CAP L 17E/19/23/25T C-PE	2.3.1	5.80 Drop 6	
Access Point	NAR	7776597-0001	CAP L 17E/19/23/25T C-PE-F1	2.3.1	5.80 Drop 6	7776597-0004
Access Point	NAR	7776597-0006	CAP L 17E/19/23/25T F-DC	2.3.1	5.80 Drop 6	
Access Point	NAR	7776597-0003	CAP L 17E/19/23/25T F-DC-F1	2.3.1	5.80 Drop 6	7776597-0006

Access Points ERA Software to Hardware Mapping

Classification	Region	ID	Description	Minimum SW Requirements	Latest Supported Version	Replacement
CAP M						
Access Point	CALA	7840984-0001	CAP M 80-85/17E/19/26 F-AC	2.8.2	5.80 Drop 6	
Access Point	CALA	7840984-0002	CAP M 80-85/17E/19/26 F-DC	2.8.2	5.80 Drop 6	
Access Point	EMEA	7838901-0001	CAP 35/35/35/35 F-AC	3.0.0	5.80 Drop 6	7851671-1003
Access Point	EMEA	7838901-0002	CAP 35/35/35/35 F-DC	3.0.0	5.80 Drop 6	7851671-1004
Access Point	EMEA	7833597-0001	CAP M 8/18/21/26 F-AC	2.8.0	5.80 Drop 6	
Access Point	EMEA	7781125-2201	CAP M 9/18/21 F-AC	2.8.0	5.80 Drop 6	7781125-0003
Access Point	EMEA	7781125-0001	CAP M 9/18/21/26 F-AC	2.4.0	5.80 Drop 6	7781125-0003
Access Point	EMEA	7781125-0003	CAP M 9/18/21/26 F-AC	2.5.0	5.80 Drop 6	
Access Point	NAR	7820689-0001	CAP M 23/23/25T/25T F-AC	2.5.0	5.80 Drop 6	
Access Point	NAR	7820689-0002	CAP M 23/23/25T/25T F-DC	2.5.0	5.80 Drop 6	
Access Point	NAR	7828333-0001	CAP M 4/70/80 F-AC	2.7.0	5.80 Drop 6	
Access Point	NAR	7828333-0002	CAP M 4/70/80 F-DC	2.7.0	5.80 Drop 6	
Access Point	NAR	7835269-0001	CAP M 6/6/7E/7E F-AC	2.8.0	5.80 Drop 6	
Access Point	NAR	7835269-0002	CAP M 6/6/7E/7E F-DC	2.8.0	5.80 Drop 6	
Access Point	NAR	7820478-0001	CAP M 7E/80-85/17E/19 F-AC	2.5.0	5.80 Drop 6	
Access Point	NAR	7820478-0002	CAP M 7E/80-85/17E/19 F-DC	2.5.0	5.80 Drop 6	

CAP MX						
Access Point	NAR	7830127-0001	CAP MX 6/7E/80-85/17E/19/23/25T F-AC	2.8.2	5.80 Drop 6	
Access Point	NAR	7830127-0002	CAP MX 6/7E/80-85/17E/19/23/25T F-DC	2.8.2	5.80 Drop 6	

Note: CAP MX and CAP H produced since the second half of 2023 require SW V4.15.20 or newer. See the customer communication CC-10127 for additional details.

CAP H						
Access Point	AUS	7843410-0002	CAP H 7/23T/26 F-AC-F1	2.8.1	5.80 Drop 6	7843410-0005
Access Point	AUS	7843410-0001	CAP H 7/23T/26 F-AC-F1-APE	2.8.1	5.80 Drop 6	7843410-0005
Access Point	AUS	7843410-0005	CAP H 7/23T/26 F-AC-F1-APE	4.15.10	5.80 Drop 6	
Access Point	AUS	7843400-0002	CAP H 85/9/18/21 F-AC-F1	2.8.1	5.80 Drop 6	
Access Point	AUS	7843400-0001	CAP H 85/9/18/21 F-AC-F1-APE	2.8.1	5.80 Drop 6	
Access Point	CALA	7841153-0002	CAP H 80-85/17E/19/26 F-AC-F1	2.8.2	5.80 Drop 6	None
Access Point	CALA	7841153-0001	CAP H 80-85/17E/19/26 F-AC-F1-APE	2.8.2	5.80 Drop 6	None
Access Point	CALA	7841153-0004	CAP H 80-85/17E/19/26 F-DC-F1	2.8.2	5.80 Drop 6	None
Access Point	CALA	7841153-0003	CAP H 80-85/17E/19/26 F-DC-F1-APE	2.8.2	5.80 Drop 6	None
Access Point	EMEA	7841175-0002	CAP H 4/4 F-AC-F1	2.8.0.400	5.80 Drop 6	
Access Point	EMEA	7841175-0001	CAP H 4/4 F-AC-F1-APE	2.8.0.400	5.80 Drop 6	7841175-0002
Access Point	EMEA	7841031-0002	CAP H 7-8/18/21/26 F-AC-F1	2.8.2	5.80 Drop 6	
Access Point	EMEA	7841031-0001	CAP H 7-8/18/21/26 F-AC-F1-APE	2.8.2	5.80 Drop 6	7841031-0002
Access Point	EMEA	7834113-0005	CAP H 7-8/9 F-AC-F1-APE	2.8.0	5.80 Drop 6	
Access Point	EMEA	7834113-0002	CAP H 7-8/9/18/21 F-AC-F1	2.8.0	5.80 Drop 6	
Access Point	EMEA	7834113-0001	CAP H 7-8/9/18/21 F-AC-F1-APE	2.8.0	5.80 Drop 6	7834113-0002

Access Points ERA Software to Hardware Mapping

Classification	Region	ID	Description	Minimum SW Requirements	Latest Supported Version	Replacement
Access Point	EMEA	7772983-0002	CAP H 8/9/18/21 F-AC-F1	2.6.0	5.80 Drop 6	
Access Point	EMEA	7772983-0001	CAP H 8/9/18/21 F-AC-F1-APE	2.6.0	5.80 Drop 6	7772983-0002
Access Point	EMEA	7841176-0002	CAP H 9R F-AC-F1	2.8.0.400	5.80 Drop 6	
Access Point	EMEA	7841176-0001	CAP H 9R F-AC-F1-APE	2.8.0.400	5.80 Drop 6	7841176-0002
Access Point	EMEA	7821740-0008	CAP H 9/18/21 F-AC-F1	2.8.0	5.80 Drop 6	
Access Point	EMEA	7821740-0007	CAP H 9/18/21 F-AC-F1-APE	2.8.0	5.80 Drop 6	7821740-0008
Access Point	EMEA	7821740-0002	CAP H 9/18/21/26 F-AC-F1	2.6.0	5.80 Drop 6	
Access Point	EMEA	7821740-0001	CAP H 9/18/21/26 F-AC-F1-APE	2.6.0	5.80 Drop 6	7821740-0002
Access Point	EMEA	7821740-0006	CAP H 18/21/26 F-AC-F1	2.8.0	5.80 Drop 6	
Access Point	EMEA	7821740-0005	CAP H 18/21/26 F-AC-F1-APE	2.8.0	5.80 Drop 6	7821740-0006
Access Point	EMEA	7844739-0002	CAP H 23T/26 F-AC-F1	2.8.1	5.80 Drop 6	
Access Point	EMEA	7844739-0001	CAP H 23T/26 F-AC-F1-APE	2.8.1	5.80 Drop 6	7844739-0002
Access Point	EMEA	7836123-0002	CAP H 26/26T F-AC-F1	2.8.0	5.80 Drop 6	
Access Point	EMEA	7836123-0001	CAP H 26/26T F-AC-F1-APE	2.8.0	5.80 Drop 6	7836123-0002
Access Point	EMEA	7849084-0002	CAP H 35HT/35HT F-AC-F1	4.15.10	5.80 Drop 6	
Access Point	EMEA	7850236-0002	CAP H 35LT/35LT F-AC-F1	4.15.10	5.80 Drop 6	
Access Point	NAR	7825719-0002	CAP H 7E/80-85/17E/19 F-AC-F1	2.6.0	5.80 Drop 6	
Access Point	NAR	7825719-0001	CAP H 7E/80-85/17E/19 F-AC-F1-APE	2.6.0	5.80 Drop 6	7825719-0002
Access Point	NAR	7825719-0004	CAP H 7E/80-85/17E/19 F-DC-F1	2.6.0	5.80 Drop 6	
Access Point	NAR	7825719-0003	CAP H 7E/80-85/17E/19 F-DC-F1-APE	2.6.0	5.80 Drop 6	7825719-0004
Access Point	NAR	7825730-0002	CAP H 17E/17E/19/19 F-AC-F1	2.6.0	5.80 Drop 6	
Access Point	NAR	7825730-0001	CAP H 17E/17E/19/19 F-AC-F1-APE	2.6.0	5.80 Drop 6	7825730-0002
Access Point	NAR	7825730-0004	CAP H 17E/17E/19/19 F-DC-F1	2.6.0	5.80 Drop 6	
Access Point	NAR	7825730-0003	CAP H 17E/17E/19/19 F-DC-F1-APE	2.6.0	5.80 Drop 6	7825730-0004
Access Point	NAR	7835476-0002	CAP H 23/23/25T/25T F-AC-F1	2.8.0	5.80 Drop 6	7835476-0006
Access Point	NAR	7835476-0006	CAP H 23/23/25T/25T F-AC-F1	4.15.10	5.80 Drop 6	
Access Point	NAR	7835476-0001	CAP H 23/23/25T/25T F-AC-F1-APE	2.8.0	5.80 Drop 6	7835476-0006
Access Point	NAR	7835476-0008	CAP H 23/23/25T/25T F-DC-F1	4.15.10	5.80 Drop 6	
Access Point	NAR	7835476-0004	CAP H 23/23/25T/25T F-DC-F1	2.8.0	5.80 Drop 6	7835476-0008
Access Point	NAR	7835476-0003	CAP H 23/23/25T/25T F-DC-F1-APE	2.8.0	5.80 Drop 6	7835476-0008

Note: CAP MX and CAP H produced since the second half of 2023 require SW V4.15.20 or newer. See the customer communication CC-10127 for additional details.

Access Points ERA Software to Hardware Mapping

Classification	Region	ID	Description	Minimum SW Requirements	Latest Supported Version	Replacement
UAP2						
Access Point	EMEA	7845389-1037	UAP 2 18/21/35LT/35HT F-DC	5.80 Drop 6	5.80 Drop 6	
Access Point	EMEA	7845389-1016	UAP2 18/21 F-DC	4.15.10	5.80 Drop 6	
Access Point	EMEA	7845389-0003	UAP2 35LT/35HT C-PE	4.15.10	5.80 Drop 6	
Access Point	EMEA	7845389-1003	UAP2 35LT/35HT F-DC	4.15.10	5.80 Drop 6	7845389-1036
Access Point	EMEA	7845389-1036	UAP2 35LT/35HT F-DC	4.15.10	5.80 Drop 6	
Access Point	EMEA	7845389-0013	UAP2 7-8/9/18/21 C-PE	4.15.10	5.80 Drop 6	
Access Point	EMEA	7845389-1013	UAP2 7-8/9/18/21 F-DC	4.15.10	5.80 Drop 6	
Access Point	EMEA	7845389-0009	UAP2 9/18/21/26 C-PE	4.15.10	5.80 Drop 6	
Access Point	EMEA	7845389-1009	UAP2 9/18/21/26 F-DC	4.15.10	5.80 Drop 6	
Access Point	NAR	7845389-0038	UAP 2 17E/19/26/35IC C-PE	5.80 Drop 6	5.80 Drop 6	
Access Point	NAR	7845389-1038	UAP 2 17E/19/26/35IC F-DC	5.80 Drop 6	5.80 Drop 6	
Access Point	NAR	7845389-0025	UAP2 17E/19 C-PE	5.0.0	5.80 Drop 6	
Access Point	NAR	7845389-1025	UAP2 17E/19 F-DC	5.0.0	5.80 Drop 6	
Access Point	NAR	7845389-0031	UAP2 17E/19/25T/37T C-PE	5.0.0	5.80 Drop 6	
Access Point	NAR	A7845389-0031	UAP2 17E/19/25T/37T C-PE (TAA Compliant)	5.0.0	5.80 Drop 6	
Access Point	NAR	7845389-1031	UAP2 17E/19/25T/37T F-DC	5.0.0	5.80 Drop 6	
Access Point	NAR	7845389-0030	UAP2 25T/34T/37T/37T C-PE	5.0.0	5.80 Drop 6	
Access Point	NAR	7845389-1030	UAP2 25T/34T/37T/37T F-DC	5.0.0	5.80 Drop 6	
Access Point	NAR	7845389-0028	UAP2 25T/37T C-PE	5.0.0	5.80 Drop 6	
Access Point	NAR	7845389-1028	UAP2 25T/37T F-DC	5.0.0	5.80 Drop 6	
Access Point	NAR	7845389-0029	UAP2 34T/37T C-PE	5.0.0	5.80 Drop 6	
Access Point	NAR	7845389-1029	UAP2 34T/37T F-DC	5.0.0	5.80 Drop 6	
Access Point	NAR	7845389-0032	UAP2 7E/17E/19/37T C-PE	5.0.0	5.80 Drop 6	
Access Point	NAR	7845389-1032	UAP2 7E/17E/19/37T F-DC	5.0.0	5.80 Drop 6	
Access Point	NAR	7845389-0034	UAP2 80-85/17E/19/37T C-PE	5.0.0	5.80 Drop 6	
Access Point	NAR	7845389-1034	UAP2 80-85/17E/19/37T F-DC	5.0.0	5.80 Drop 6	
Access Point	NAR	7845389-0033	UAP2 80-85/25T/34T/37T C-PE	5.0.0	5.80 Drop 6	
Access Point	NAR	7845389-1033	UAP2 80-85/25T/34T/37T F-DC	5.0.0	5.80 Drop 6	

Access Points ERA Software to Hardware Mapping

Classification	Region	ID	Description	Minimum SW Requirements	Latest Supported Version	Replacement
CAP L2						
Access Point	EMEA	7845390-0001	CAP L2 18/21/23T/26 C-PE	4.15.10	5.80 Drop 6	
Access Point	EMEA	7845390-1001	CAP L2 18/21/23T/26 F-DC	4.15.10	5.80 Drop 6	
Access Point	EMEA	7845390-0003	CAP L2 35LT/35HT C-PE	4.15.10	5.80 Drop 6	
Access Point	EMEA	7845390-1003	CAP L2 35LT/35HT F-DC	4.15.10	5.80 Drop 6	7845390-1036
Access Point	EMEA	7845390-1036	CAP L2 35LT/35HT F-DC	4.15.10	5.80 Drop 6	
Access Point	EMEA	7845390-0009	CAP L2 9/18/21/26 C-PE	4.15.10	5.80 Drop 6	
Access Point	EMEA	7845390-1009	CAP L2 9/18/21/26 F-DC	4.15.10	5.80 Drop 6	
Access Point	NAR	7845390-0007	CAP L2 17E/19/23/25T C-PE	4.15.10	5.80 Drop 6	
Access Point	NAR	7845390-1007	CAP L2 17E/19/23/25T F-DC	4.15.10	5.80 Drop 6	
Access Point	NAR	7845390-0008	CAP L2 6/7E/80-85 C-PE	4.15.10	5.80 Drop 6	
Access Point	NAR	7845390-1008	CAP L2 6/7E/80-85 F-DC	4.15.10	5.80 Drop 6	
Access Point	NAR	7845390-0018	CAP L2 C-Band C-PE	4.15.10	5.80 Drop 6	
Access Point	NAR	7845390-1018	CAP L2 C-Band F-DC	4.15.10	5.80 Drop 6	
Access Point	NAR	7845390-0035	CAP L2 34T/37T/37T C-PE	5.50 Drop 6	5.80 Drop 6	
Access Point	NAR	7845390-1035	CAP L2 34T/37T/37T F-DC	5.50 Drop 6	5.80 Drop 6	

CAP M2						
Access Point	EMEA	7851671-1003	CAP M2 35LT/35HT F-AC	4.15.10	5.80 Drop 6	
Access Point	NAR	7851671-1001	CAP M2 C-Band F-AC	4.15.10	5.80 Drop 6	
Access Point	NAR	7851671-1002	CAP M2 C-Band F-DC	4.15.10	5.80 Drop 6	
Access Point	NAR	7856326-1003	CAP M2 34T/37T/37T F-AC-F1	5.50 Drop 6	5.80 Drop 6	
Access Point	NAR	7856326-1004	CAP M2 34T/37T/37T F-DC-F1	5.50 Drop 6	5.80 Drop 6	
Access Point	NAR	7856326-1010	CAP M2 17E/19/23/25T F-AC-F1	5.50 Drop 6	5.80 Drop 6	
Access Point	NAR	7856326-1011	CAP M2 17E/19/23/25T F-DC-F1	5.50 Drop 6	5.80 Drop 6	

For additional information, please contact Technical Support

Telephone Helplines: Call one of the Telephone Helpline numbers listed below to get live support, 24 hours a day.

Global 24X7

+1 888-297-6433 (Toll free for U.S. and Canada)

EMEA 8:00-17:00 (UTC +1)

+ 800 73732837 (Toll free for parts of EMEA and Australia)
+ 49 909969333 (Toll charge incurred)

Online Support: Use the QR code on the right or click on the following URL to submit a request to Technical Support. <https://wisupport.commscope.com/>

